


State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)

Date of Notification (1) 7-6-16		Name of Building Owner/Operator (2) DEPT OF THE ARMY	
Agencies Notified <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/> DEP <input checked="" type="checkbox"/> DOL <input checked="" type="checkbox"/> DOH <input checked="" type="checkbox"/> DCA	Type Notification <i>Postponed</i> <input checked="" type="checkbox"/> Initial <input checked="" type="checkbox"/> Amended Amendment #1 _____ <input type="checkbox"/> Emergency (including justification) <input type="checkbox"/> Cancellation		Street Address P.O. BOX 1600
			City, State, Zip Code HUNTSVILLE, PA 35807
		Name of Contact	Telephone Number 256-895-1694

FACILITY INFORMATION			
Name of Facility Where Abatement is Taking Place (3) FORT MONMOUTH ARMY BASE		Type of Facility (4) <input type="checkbox"/> School (K-12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input checked="" type="checkbox"/> Other (i.e. private & commercial buildings, homes, etc.)	
Street Address 502 BREWER AVENUE		Square Feet 200,000	# of Floors 1
City (5) OCEANPORT		Bldg. Age 100	
County (6) MONMOUTH	County Code (7) (STATE USE ONLY) _____	Current Use (Prior if being demolished) VACANT (ARMY BASE)	
Name of Monitoring Firm Hired by Building Owner (8) AET, INC.		ASCM No.	Name of Abatement Contractor (9) PEPPER ENVIRONMENTAL SERVICES, INC.
Street Address 28 N. PENNELL ROAD		Street Address 2251 FRALEY STREET	
City, State, Zip Code MEDIA, PA 19063		City, State, Zip Code PHILADELPHIA, PA 19137	
Project Manager for Monitoring Firm ERIC SUTHERLAND		Telephone No. 610-891-0114	Telephone No. 215-533-5155
License No. 01166			
Start Date (10) 7-6-16	Scheduled Completion Date (11) 8-31-16	Name of OSHA Monitor AET, INC.	
Occupancy Status During Abatement (Check Only One) <input checked="" type="checkbox"/> Facility Closed/Vacated During Entire Period of Abatement <input type="checkbox"/> Abatement Performed Outside of Normal Facility Hours Other - Describe: _____		Street Address 28 N. PENNELL ROAD	
		City, State, Zip Code MEDIA, PA 19063	

Scope of Work (Check All That Apply)			
<input type="checkbox"/> ≥3 sf or ≥3 lf	<input checked="" type="checkbox"/> Renovation	<input checked="" type="checkbox"/> Full Containment with Negative Pressure	
<input checked="" type="checkbox"/> ≥160 sf or ≥260 lf	<input type="checkbox"/> Demolition	<input checked="" type="checkbox"/> Mini-Enclosure	
		<input checked="" type="checkbox"/> Glovebag Procedure	
		<input checked="" type="checkbox"/> Non-Exempted (*) and Non-Friable Procedure	

Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
				SEE ATTACHED SHEET					

Name of Registered Waste Hauler SERVICE TRANSPORT GROUP		NJDEP Waste Hauler ID No.	Cubic Yards of Waste	Name of Registered Landfill A & L SALVAGE	
City, State NEW CASTLE, DE		Disposal Date		City, State LIBSON, OH	
Completed by JENNIFER NIVEN	Title DIR. OF OPERATIONS	Signature 		Date 7-6-16	

Appendix D

PRICE SPREADSHEET

Contractor may provide additional relevant fixed unit pricing if needed to complete the effort. Unit Prices included herein have no bearing of the contract price and are proposed as an estimate only to provide a basis for determining a fair and reasonable price. This is a performance based contract and the inclusion of unit prices in the proposal shall in no way be construed as the Government is procuring a specified number of units of any given service.

Task	Task Name	Task Pricing	Unit Price	If priced per unit		Total Price
				Units	Number of Units	
1	Work Plans (to include all Drafts/ Final Documents, Draft QASP and comment response)	FFP		LS		4,641
2	Building 209					
2.1	1st Fl, SW; Removal of ACM 50 LF	FFP		LS		2,500
2.2	1st Fl, NC; Removal of ACM 50 LF	FFP		LS		2,500
2.3	1st Fl, NW; Removal of ACM 50 LF	FFP		LS		2,500
3	Building 270					
3.1	Basement – Repair of 400 LF of ACM Pipe Insulation	FFP		LS		3,000
3.2	Basement – Repair of 40 LF of ACM Pipe Insulation	FFP		LS		1,200
3.3	1 St Fl – Repair of 15 LF of ACM Pipe Insulation	FFP		LS		200
3.4	2nd Fl – Room 4 Removal of 10 SF of ACM TSI Debris	FFP		LS		200
4	Building 271					
4.1	Basement – Removal of Flue Packing 2 SF	FFP		LS		200
4.2	Attic and Chase – Repair of 30 LF of Four Inch ACM Pipe Insulation	FFP		LS		1,200
5	Building 286					
5.1	Boil Room - 1 St Fl – Removal of 2 LF of ACM Pipe Insulation	FFP		LS		1,000
5.2	Basement – Room 024A – Removal of 1 LF of ACM Pipe Insulation	FFP		LS		100
5.3	Basement – Room 009A – Removal of 1 LF of ACM Pipe Insulation	FFP		LS		100
5.4	2 nd Fl, Womens Room – Room 024A – Removal of 50 LF of ACM Pipe Insulation	FFP		LS		2,500
6	Building 551					
6.1	Southeast – Repair 25 LF of ACM Pipe Insulation	FFP		LS		1,500
7	Building 552					
7.1	Mechanical Rm – Repair 10 LF of ACM Pipe Insulation	FFP		LS		200
7.2	Mechanical Rm – Repair 10 LF of ACM Pipe Fittings	FFP		LS		200

Task	Task Name	Task Pricing	Unit Price	If priced per unit		Total Price
				Units	Number of Units	
7.3	Outside Office – Removal 1 of ACM Pipe Fitting	FFP		LS		
8	Building 1150					100
8.1	Basement Battery Room – Repair 100 LF of ACM Duct Insulation	FFP		LS		
9	Building 1215					1,200
9.1	AC Room – Repair 26 ACM Duct Pipe Fittings	FFP		LS		
9.2	Concession/HVAC/Storage Room – Repair 12 ACM Duct Pipe Fittings	FFP		LS		300
9.3	Boiler Room – Repair 22 SF Tank Insulation	FFP		LS		300
9.4	Boiler Room – Removal 90 SF Boil Insulation	FFP		LS		500
	OPTIONAL TASKS					3,500
10	Building 283					
10.1	Basement – Corridor – Removal of 133 LF of ACM Pipe Insulation	FFP		LS		
10.2	1 st Fl – Room 107 – Repair of 5 LF of ACM Pipe Insulation	FFP		LS		4,200
10.3	1 st Fl – Womens Room – Repair of 10 LF of ACM Pipe Insulation	FFP		LS		200
10.4	1 st Fl – Womens Room (former mens room) – Repair of 5 LF of ACM Pipe Insulation	FFP		LS		300
10.5	1 st Fl – Janitors Closet by room 162– Repair of 20 LF of ACM Pipe Insulation	FFP		LS		300
10.6	1 st Fl – Stairwell by room 162– Repair of 25 LF of ACM Pipe Insulation	FFP		LS		200
10.7	1 st Fl – Wing North– Repair of 800 LF of ACM Pipe Insulation	FFP		LS		200
10.8	2 nd Fl –Room 231– Repair of 10 LF of ACM Pipe Insulation	FFP		LS		8,250
10.9	2 nd Fl –Room 230– Removal of 1 LF of ACM Debris	FFP		LS		500
10.10	2 nd Fl –Throughout Wing on West- Removal of 20,000 SF of 2 X 2 Tiles	FFP		LS		100
10.11	Basement, Crawlspace 2– Repair of 800 LF of ACM Pipe Insulation	FFP		LS		84,000
10.12	Basement, Crawlspace 2– Removal of 5200 SF of ACM Debris with Detailed cleaning	FFP		LS		8,000
10.13	Basement, Crawlspace 1– Repair of 2000 LF of ACM Pipe Insulation	FFP		LS		26,000
10.14	Basement, Crawlspace 1– Removal of 13,780 SF of ACM Debris with Detailed cleaning	FFP		LS		40,000
	CONTIGUENCY TASKS					65,520
11.1	Repair of 4000 LF of ACM Pipe Insulation. Provide a cost per unit up to 4000 LF	FFP		LS 15.00		
11.2	Repair of 100 EA Pipe Fittings. Provide a cost per unit up to 100 Pipe Fittings	FFP		LS 20.00		
11.3	Removal of 1000 LF of ACM Pipe Insulation. Provide a cost per unit up to 1000 LF	FFP		LS 25.00		
11.4	Removal of 100 EA Pipe Fittings. Provide a cost	FFP		LS 25.00		